

The Theme for June 2019 is: Nuisance

Your Health and Safety

Our Environment

Quality Requirements

Dust:

PPE should be worn as detailed in COSHH Assessments and RAMS (e.g. FFP3 Masks).

Cover aggregates / loose materials. Position stock piles as far from residential areas as possible.

Clean the wheels of plant and vehicles in a designated area, to remove mud and dust.

Pave heavily used haul routes and regularly sweep to prevent dust build up.

Emissions / Odour:

Service vehicles / plant regularly. Do not leave engines, generators or plant on when not in use.

Take account of wind conditions before starting activities likely to emit fumes and smoke (to reduce pollution and odour spreading).

Control deliveries to minimise queuing.

Do not burn any waste on site.

Vibration:

Routine medicals must be undertaken for all employees exposed to vibration.

HAVs monitoring and records must be kept and submitted to: Treatment.havs@stantec.com

Activities that may cause damage to surrounding structures must be approved by site management with control measures in place.

Seek alternative methods of working / tools to reduce the exposure to vibration.

Noise:

Maintain plant and tools.

Do not work outside of the permitted working hours.

Noise monitoring must be in place with the appropriate controls measures used (exclusion zones, screens, hearing protection).

Use noise suppression equipment to minimise nuisance (e.g. covers on compressors, silences on generators).

If you are approached with a complaint by a member of the public, be polite to the individual and report the issue to site management.